



LEGEND

- 1

Update PA system in the chancel and pulpit.

2

New handrail.

3

Existing pulpit removed.

4

New oak shelf, set at the height of the frontal lid.

5

Remove the childrens choir stalls on each side of the chancel. Move the book rest back in front of the adult choir stall.

6

Lectern re-positioned.

7

Existing portable chairs which match those used by the priests, servers and choir, will provide flexible seating in the chancel.

8

Sides of the top step extended and finished in stone to match the existing. Side arms of rearados angled to allow priest to officiate from behind altar.
- 9

New low level musical instruments cupboard and new music cupboard.

10

Raise existing radiator to new floor level.

11

New light, moveable, music stands.

12

Dais area reconfigured and floor level raised to match that of the chancel. Wide step infront of dais will provide a space from which the communion can be administered.

13

2 pews removed. Frontal retained to form the front of the new block of pews.

14

New heating system see consultants report.
- 15

New glazed screen to tower arch.

16

New radiator.

17

Rope barrier with antique bronze hooks (colour red). To be used only when ramp is in use.

18

Foldable, moveable portable ramp (760x1590) by Portaramp.

19

New handrail made from redundant pews to maintain existing design and create furniture uniformity.

20

Proposed storage location of temporary ramp.

21

Proposed storage location of choir music stand.
- Amendments:

G - 15.06.15 Existing pulpit replaced with lectern. Dais altered to suit changes.

F - 12.11.14 Annotation revised.

E - 10.10.14 Moveable ramp added.

D - 19.06.14 Pulpit position adjusted and ramp omitted.

C - 27.05.14 Ramp design altered.

B - 01.11.13 Changes as per clients requirements.

A - 18.01.13 Changes as per clients requirements.