

# Site risk assessment form

1

Property	The Green	Location	Lympstone	Ref No.	
Council	Lympstone Parish	Chairman	Cllr Nick Linfoot	Date	06/03/2022
Activity	Visitor Site Risk Assessment				

#### **Description:**

This is a risk assessment of the visitor routes at The Green split in to high, medium and low-level use.

The use of the field takes account of different levels of use and types of activity, reflecting the numbers of people that use the area and the time that they spend in that area. The risk assessment follows the guiding principles of the 'managing visitor safety in the countryside; principles & practice' guidance produced by the Visitor Safety in the Countryside Group and is relevant for visitors to site and contractors. Any specific activities carried out on the site are covered through other risk assessments. The Green is a paved area situated on The Strand in the centre of the village. It has two benches and an adjacent crossing from the Highway to the estuary. It is used as a resting place for pedestrians and cyclists passing by. Alongside the area is a locked post to prevent vehicular access to the estuary.

#### Beach hazards

LPC does not take responsibility for hazards at sea, this role is taken on by other organisations such as Heritage England, the Harbour Board and Exe Estuary Partnership Management. The estuary is not manned.

### Severity of the hazard:

How serious are the consequences likely to be? Extreme (fatality) / Serious (major injury or serious ill health / Moderate (minor injury)

### Likelihood of the event:

How likely is it that the event will occur? Remote / Possible / Likely

## Adequacy of controls:

Are existing precautions adequate? Good (most precautions in place) / Fair (some deficiencies) / Weak (serious deficiencies)



# Site risk assessment form

Entrance access – low risk					
Nature of hazard	Groups at risk	Current precautions	Estimation of risk	Potential additional precautions	
Vehicle to vehicle contact	Visitors and contractors	The entrance to The Green is kept clear and free of vegetation.  A 'No parking' sign is installed at the entrance to the road leading to the estuary and alongside the Green. The vehicular access post to the estuary is locked unless permission is sought.	Severity of hazard : low Likelihood of event : possible Adequacy of controls : good	Replacement post agreed to be ordered by LPC (Feb 20). Clerk to order and replace old post at base of access way to estuary.	
Vehicles on highway encountering pedestrians.	Visitors and contractors	The paved area is well-maintained by LPC handyman. The area is open space for clear visibility to both pedestrians and road users.	Severity of hazard : low Likelihood of event : remote Adequacy of controls : good		
Trip/slips due to uneven surfaces.	Visitors and contractors	Paths are inspected in quarterly check and repaired as required.	Severity of hazard : low Likelihood of event : remote Adequacy of controls : good		

Benches – low risk					
Nature of hazard	Groups at risk	Current precautions	Estimation of risk	Potential additional precautions	
Damage to benches	Visitors and contractors	Seats are maintained twice a year.	Severity of hazard : Low Likelihood of event : Remote Adequacy of controls : Good		

Assessment carried out by	Lucy Tyrrell	Job title	Clerk to Lympstone Parish Council
---------------------------	--------------	-----------	-----------------------------------